


# PLASMA TORCH PW 80

DIAGRAM PW 80



## PW 80

### Welding torches Plasma torch

The PW series of air cooled PLASMA torches give the operator a high manageability due to its ergonomic and easy design driving. They have a patented safety button to avoid activation by mistake.

### Exploded

- 1 Torch head kit
- 2 Safety button
- 3 Handle
- 4 screws
- 5 Case
- 6 Compass carriage kit
- 7 Cooling tube
- 8 (See spare parts on page Xxx)

### Main features

- 80A AIR / GAS N2
- EN 60974-7
- 60% Duty Cycle
- 6m cable

